Figures



Scale	Date
	Mar 2011

ANDERSON - MULHOLLAND & ASSOCIATES, INC.
WHITE PLAINS, NEW YORK

Figure 1

Building 5 Expansion Area

Bristol-Myers Squibb Manufacturing Company
Humacao, Puerto Rico


BLDG NUM. 37
A/C UNITS
BLDG NUM. 42
BLDG. NUM. 43
BUILDING 5 EXPA
BLDG. NUM. 30
STREET-F
D
C
B
A
SUB-STATION BLDG
BLDG. NUM. 5
BLDG. NUM. 6
BLDG. NUM. 16
STREET-B
BLDG. NUM. 17
BLDG NUM. 15
PARKING - C
PARKING - B
PARKING - A



Figure 2

Supplemental Soil Boring Locations

Bristol-Myers Squibb Manufacturing Company
Humacao, Puerto Rico

PREPARED BY: ANDERSON - MULHOLLAND & ASSOC, INC.


P-6
P-7
P-5
P-8
P-4
I-19
I-18
I-17
I-16
P-3
I-15
I-14
I-13
I-12
I-11
I-10
I-9
I-8
I-7
P-2
I-7A
P-1
I-6
I-5
I-4
I-3
I-2
EXISTING BUILDING 5
LEGEND
PLANNED BUILDING 5 EXPANSION
I-1
FOOTPRINT SOIL BORING
P-1
PERIMETER SOIL BORING
PRE-DESIGN SOIL BORING (2007)
MONITORING WELL
AREA C & D EXCAVATION AREA
ORIGINAL SCHEDULED AREA D REMOVAL
0
20
40
60
80
GRAPHIC SCALE IN FEET

(6-7)
0.249 J
0.57 U
0.057 U
1.84
0.12 U
0.23 U
0.057 U
6.04

	I-7A (4-4.5)	I-7 (10-11)
MIBK	0.0055 U	1080
Acetone	0.011 U	127
Benzene	0.0011 U	0.0335 J
Ethylbenzene	0.0011 U	1320
Isopropyl Alcohol	0.12 U	500
Methanol	0.24 U	1050
Toluene	0.0011 U	64.1
Xylene (total)	0.0011 U	4900

Screening Tiers	Tier 1 RCRA Subtitle D[1]	Tier 2 USEPA RSLs[2]
COC	Concentration (mg/kg)	
MIBK	330	4.6
Acetone	1600	48
Benzene	100	0.052
Ethylbenzene	100	15.6
Isopropyl Alcohol	NA	NA
Methanol	NA	32
Toluene	100	13.8
Xylene (total)	300	196

[1]Tier 1 Levels represent alternative land disposal restriction treatment standards for contaminated media (i.e., ten times the universal treatment standard) in accordance with 40CFR §268.49(c)(1)(c).

[2]Tier 2 Levels represent migration to groundwater screening levels from EPA Regional Screening Levels (November, 2011). Values shown are based on a dilution attenuation factor of 20.

NA: Screening level not developed for this COC

Concentration is greater than Tier 2 Level and less than Tier 1 Level

Concentration is greater than Tier 1 Level



A-1R3 (4.5-5)	
MIBK	0.0054 U
Acetone	0.0296
Benzene	0.0011 U
Ethylbenzene	0.0121
Isopropyl Alcohol	0.12 U
Methanol	0.25 U
Toluene	0.0011 U
Xylene (total)	0.0346

0063 U
0097 J
.0015
0012 U
.12 U
.23 U
0013 U
00088 J

I-2 (10-10.5)	
MIBK	106
Acetone	2.85
Benzene	0.079 U
Ethylbenzene	57.5
Isopropyl Alcohol	2.85
Methanol	3.32
Toluene	54.9
Xylene (total)	229

Figure 3

Distribution of COCs in Footprint Soil Borings

Bristol-Myers Squibb Manufacturing Company
Humacao, Puerto Rico

PREPARED BY: ANDERSON - MULHOLLAND & ASSOC, INC.


I-19 (8-9)
MIBK 0.0053 U
Acetone 0.0132
Benzene 0.00051 J
Ethylbenzene 0.0078
Isopropyl Alcohol 0.12 U
Methanol 0.23 U
Toluene 0.0011 U
Xylene (total) 0.0232
I-18 (7-8)
MIBK 0.0053 U
Acetone 0.0077 J
Benzene 0.00031 J
Ethylbenzene 0.0017
Isopropyl Alcohol 0.11 U
Methanol 0.22 U
Toluene 0.0011 U
Xylene (total) 0.0119
I-17 (10-11)
MIBK 34.9
Acetone 30 U
Benzene 3 U
Ethylbenzene 1710
Isopropyl Alcohol 1.22
Methanol 0.301
Toluene 4.42
Xylene (total) 5550
I-14 (8.5-9.5)
MIBK 0.0059 U
Acetone 0.012
Benzene 0.00042 J
Ethylbenzene 0.0325
Isopropyl Alcohol 0.13 U
Methanol 0.25 U
Toluene 0.0012 U
Xylene (total) 0.0826
I-15 (5-6)
MIBK 0.0051 U
Acetone 0.0078 J
Benzene 0.00076 J
Ethylbenzene 0.00038 J
Isopropyl Alcohol 0.12 U
Methanol 0.24 U
Toluene 0.001 U
Xylene (total) 0.0075
I-13 (12.5-13.5)
MIBK 0.0058 U
Acetone 0.0201
Benzene 0.0016
Ethylbenzene 0.00031 J
Isopropyl Alcohol 0.12 U
Methanol 0.731
Toluene 0.0012 U
Xylene (total) 0.0113
I-12 (9.5-10.5)
MIBK 127
Acetone 69.8
Benzene 0.06 U
Ethylbenzene 361
Isopropyl Alcohol 40.1
Methanol 0.23 U
Toluene 1.06
Xylene (total) 1270
I-6 (8.5-9.5)
MIBK 0.0062 U
Acetone 0.012 U
Benzene 0.0012 U
Ethylbenzene 0.0012 U
Isopropyl Alcohol 0.13 U
Methanol 0.27 U
Toluene 0.0012 U
Xylene (total) 0.0012 U
I-5 (9-10)
MIBK 0.0061 U
Acetone 0.0233
Benzene 0.0012 U
Ethylbenzene 0.0012 U
Isopropyl Alcohol 0.14 U
Methanol 0.28 U
Toluene 0.0012 U
Xylene (total) 0.0012 U
I-4 (5-6)
MIBK 240
Acetone 95.7
Benzene 0.76 U
Ethylbenzene 540
Isopropyl Alcohol 62
Methanol 0.487
Toluene 178
Xylene (total) 2000
I-9 (8.5-9.5)
MIBK 0.0059 U
Acetone 0.012 U
Benzene 0.00048 J
Ethylbenzene 0.0523
Isopropyl Alcohol 0.13 U
Methanol 0.26 U
Toluene 0.0012 U
Xylene (total) 2.66
I-3 (5-6)
MIBK 5.26
Acetone 11.5
Benzene 0.0192 J
Ethylbenzene 191
Isopropyl Alcohol 57
Methanol 0.25 U
Toluene 444
Xylene (total) 736
P-1
P-2
P-3
P-4
P-5
P-6
P-7
I-16
I-17
I-18
I-19
I-15
I-14
I-13
I-12
I-11
I-10
I-9
I-8
I-6
I-5
I-4
I-3
0
GRAPHIC SCAL



Figure 4

Distribution of COCs in Perimeter Soil Borings

Bristol-Myers Squibb Manufacturing Company
Humacao, Puerto Rico

PREPARED BY: ANDERSON - MULHOLLAND & ASSOC, INC.



P-6 (0-1)	
MIBK	0.0052 U
Acetone	0.0562
Benzene	0.00059 J
Ethylbenzene	0.0021
Isopropyl Alcohol	0.12 U
Methanol	0.415
Toluene	0.001 U
Xylene (total)	0.0011

P-5 (4.5-5.5)	
MIBK	0.195
Acetone	0.01
Benzene	0.00047 J
Ethylbenzene	3.83
Isopropyl Alcohol	0.12 U
Methanol	0.24 U
Toluene	0.0024
Xylene (total)	11.8

P-4 (4-5)	
MIBK	0.0064 U
Acetone	0.0304
Benzene	0.00071 J
Ethylbenzene	0.0186
Isopropyl Alcohol	0.13 U
Methanol	0.25 U
Toluene	0.0013 U
Xylene (total)	0.0731

P-3 (1-2)	
MIBK	0.0065 U
Acetone	0.013 U
Benzene	0.0013 U
Ethylbenzene	0.0124
Isopropyl Alcohol	0.12 U
Methanol	0.24 U
Toluene	0.0013 U
Xylene (total)	0.0046

P-2 (1.5-2)	
MIBK	0.0051 U
Acetone	0.0088 J
Benzene	0.001 U
Ethylbenzene	0.001 U
Isopropyl Alcohol	0.11 U
Methanol	0.22 U
Toluene	0.001 U
Xylene (total)	0.001 U

P-1 (0.5-1.5)	
MIBK	0.31 U
Acetone	0.61 U
Benzene	0.061 U
Ethylbenzene	0.911
Isopropyl Alcohol	1.15
Methanol	0.224
Toluene	0.061 U
Xylene (total)	2.5

Screening Tiers	Tier 1 RCRA Subtitle D[1]	Tier 2 USEPA RSLs[2]
COC	Concentration (mg/kg)	
MIBK	330	4.6
Acetone	1600	48
Benzene	100	0.052
Ethylbenzene	100	15.6
Isopropyl Alcohol	NA	NA
Methanol	NA	32
Toluene	100	13.8
Xylene (total)	300	196

[1]Tier 1 Levels represent alternative land disposal restriction treatment stanc for contaminated media (i.e., ten times the universal treatment standard) in accordance with 40CFR §268.49(c)(1)(c).

[2]Tier 2 Levels represent migration to groundwater screening levels from EPA Levels (November, 2011). Values shown are based on a dilution attenuation

NA: Screening level not developed for this COC

Concentration is greater than Tier 2 Level and less than Ti
Concentration is greater than Tier 1 Level

0 20 40

GRAPHIC SCALE IN FEET

Figure 5
Transect A Cell Profiles
Building 5 Area Supplemental Soil Investigation

Depth	P-1		I-6		I-5		I-4		I-3		I-2		I-1		Depth
							Ground Surface								
0	275		200	No Odor	25	No Odor	7000	STR Odor	0	No Odor	NR		20	MOD Odor	0
0.5	583	2.5	438		36		9999		66		NR		31		0.5
1	500		127		NR		9999		94		NR		19.5		1
1.5	NR		360		NR		9999		NR		NR		4000		1.5
2	NR		NR		NR		9999		NR		NR		NR		2
2.5	NR		NR		NR		NR		NR		NR		NR		2.5
3	NR		NR		NR		NR		NR		NR		NR		396
3.5	NR	SL Odor	NR		NR		NR		NR		NR		NR		3.5
4	100		129		57		3000		80		9999	STR Odor	1700	MOD-STR Odor	4
4.5	235		240		70		4000		155		9999		1200		4.5
5			450		68		9999	2000	1700	736	9999		9999		5
5.5			428		89		9999		4500		9999		9999		5.5
6			160		178		1500		700		4790		9999		6
6.5			300		NR		200	MOD Odor	105	STR Odor	9999		3500		6.5
7			NR		NR		NR		671		1000		2800		7
7.5			NR		NR		NR		NR		903		Refusal		7.5
8			1380		51		340		NR		1000				8
8.5			911	ND	19		860		NR		500				8.5
9			995		42	ND	670		NR		250				9
9.5			420		98		536		NR		9999	229			9.5
10			18	SL-MOD Odor	66		75		NR		900				264
10.5			NR		129		NR		NR		132				10.5
11			NR		NR		NR		NR		NR				11
11.5			NR		NR		NR		NR		NR				11.5
12			590						NR		9999	STR Odor			12
12.5			40						Refusal		9999				12.5
13			310								9999				13
13.5											1300				13.5
14											200				14
14.5											20				14.5
15											20				15
15.5											40				15.5
							Impacted Soil Volume (cubic yards)								
	0		0		0		75		56		78		56		

Notes:
NR = No Recovery
SL = Slight
MOD = Moderate
STR = Strong

Impacted soil

Potentially impacted soil

Figure 6
Transect B Cell Profiles
Building 5 Area Supplemental Soil Investigation

Depth	P-2		I-11	I-10		I-9		I-8		I-7/I-7A		D-26/A-1R3/A-1R3A			D-27	D-28	D-29		Depth
Ground Surface																			
0	15	No Odor		890	No Odor	3	No Odor	91	No Odor	9	No Odor	0							0
0.5	87		Refusal	150		46		354		4					0	1	0		0.5
1	71			30		85		484		15		0	0		0	0	1		1
1.5	247	ND		NR		288		NR		11					9	Area D Removal	2		1.5
2	NR			NR		NR		NR		18		0			99		51		2
2.5	NR			NR		NR		NR		36					308		869		2.5
3	NR			NR		NR		NR		NR			396				982		3
3.5	NR			Refusal		NR		NR		NR			400				209		3.5
4	20	No Odor				16		140		1477	ND		250				1078		4
4.5	70					190		140		21	No Odor		400	0.035	65				4.5
5	69					312	SL Odor	578		38		0	400		60				5
5.5	30					64		240		66							1017		5.5
6						30		528		20	MOD Odor	0.5					327		6
6.5						NR		NR		70		0		5.4			708	1830	6.5
7						NR		NR		NR		2	1				103		7
7.5						NR		NR		NR		2.9					349		7.5
8						94		824	SL Odor	41		2.3					321		8
8.5						330	2.66	636		244		45.4					330		8.5
9						81		738		1030		310	2679				207		9
9.5						90		770		995		2192		394			83		9.5
10						175	MOD Odor	1247	MOD Odor	9999	4900	555	264				124		10
10.5						NR		NR		9999		153					650		10.5
11						NR		NR		2300		48	1704				481		11
11.5						71		NR		NR		44					112		11.5
12								9999		9999							6		12
12.5								9999		NS							10		12.5
13								9999		NS			0				8		13
13.5								2000		NS						307			13.5
14								9999	0.001	NS					301	64			14
14.5								9999		NS					127	16			14.5
15								1340							3	7			15
15.5															1				15.5
Impacted Soil Volume (cubic yards)																			
	0		0	0		0		83		125		83					187		

Notes:
NR = No Recovery
SL = Slight
MOD = Moderate
STR = Strong

Impacted soil

Potentially impacted soil

Figure 7
Transect C Cell Profiles
Building 5 Area Supplemental Soil Investigation

Depth	P-3		I-15		I-14		I-13		I-12		D-31		D-32		D-33		D-34/P-9			D-35		Depth
											Ground Surface											
0	230		86	No Odor	12	No Odor	11	No Odor	745	MOD Odor	700		0		0		0		290	No Odor	0		0
0.5	430	0.0046	350		234		180		922		1400	7.49	2194		0		0		580		0		0.5
1	250		NR		39		19		81		360		65		0		0		680		4	5.89	1
1.5	200		NR		25		82		237		85				0		0		380		3		1.5
2	NR		NR		90		NR		NR		76		0				0		390		31		2
2.5	NR		NR		NR		NR		NR		25		0				0		1400		87		2.5
3	NR		NR		NR		NR		NR		42		0		396		0		NR		9		3
3.5	NR		NR		NR		NR		NR				0				5		NR		21		3.5
4	90	No Odor	924		150	SL Odor	9.9	SL Odor	112	No Odor	93		0.3		0		0	0.02	160		44		4
4.5	73		946		190		38		310		0		36		0		36		9999		62		4.5
5	78		480	0.0075	168		40		61		23		8.2		4		1030		9999	1750	24		5
5.5	76		1900		382		153		161		18		0		0	0.195	182		9999		1		5.5
6			270		364		194		521		12.5		0		1		1262		2420		8	0.022	6
6.5			548		194		121		NR		14		0	1.27	52		1369	576	1550	STR Odor	0		6.5
7			NR		NR		NR		NR		240		59		0		83		2021		1		7
7.5			NR		NR		NR		NR		286		97				26		2090		0		7.5
8			402	SL-MOD Odor	437		50	MOD Odor	1103	SL-STR Odor	3.6		0		0		1104				42		8
8.5			365		570	0.0826	75		360		173		0		42	45.3	292				4		8.5
9			270		630		1080		4000		199		0		0		12				0		9
9.5			295		205		330		9999	1270	346	78.2 (MIBK)	23				11				0		9.5
10			142		131	No Odor	48	No Odor	9999		664		79		264		26				0		10
10.5			313		120		125		400		24.2		446				1				0		10.5
11			30		108		58		404	MOD Odor	10.3		9999	4030	0		0				0		11
11.5					201		50		NR				7157								0		11.5
12					55		440		555				113										12
12.5					61	No-MOD Odor	637	0.0113	40				81										12.5
13					75		215		22				428										13
13.5					105		218						495										13.5
14					77		60						293										14
14.5					86								11										14.5
15													41										15
15.5													70										15.5
											Impacted Soil Volume (cubic yards)											
	0		0		0		0		94		21		73		0		94				0		

Notes:
NR = No Recovery
SL = Slight
MOD = Moderate
STR = Strong

Impacted soil

Potentially impacted soil

Figure 8
Transect D Cell Profiles
Building 5 Area Supplemental Soil Investigation

Depth	P-4		I-19		P-5		I-18		I-17		I-16		D-36		P-8		D-37	Depth
									Ground Surface									
0	180		0	No Odor	60	No Odor	3400	No Odor	244	No Odor	73	No Odor			2200	No Odor		0
0.5	87		0.1		47		9999		360		194		0		680		0	0.5
1	500		0.5		NR		9999		488		96		0		393		0	1
1.5	260		1.9		NR		4896		507		111				440			1.5
2	400		1.4		NR		9999		NR		296		0		NR		0	2
2.5	NR		0.8		NR		NR		NR		NR				NR			2.5
3	NR		NR		NR		NR		NR		NR				396			3
3.5	NR		NR	No Odor	NR		NR		NR		NR				NR			3.5
4	75	0.0731	0.3		NR		2170	No Odor	1052	STR Odor	602		0		1228	0.0011	0	4
4.5	1000		0.9		103	11.8	2100		359		423		0		900			4.5
5	550		2.6	SL Odor	772		819		828		308		0		320		0	5
5.5	1000	No Odor	3.5		422		495		1429		988	6.04	0		300	SL Odor		5.5
6	100		3.7				989		1433		1267		0	2.32	441		0	6
6.5			4.4				1286		339		913		0		260			6.5
7			2				9999	0.0119	NR		NR		11		243		0	7
7.5			2.3				9999		NR		NR	No Odor	5					7.5
8			205	0.0232			1		844		445		68				0	8
8.5			102				2.1		9999		199		4					8.5
9			83				2.2		9999		643	MOD Odor	4				0	9
9.5			25				3.8		9999		200		70					9.5
10			27				NR		9999	5550	95		392	283	264		0	10
10.5			29				NR		9999		164		348					10.5
11			20				2.5		450		120		0				0	11
11.5			33	SL Odor			2.5		177				0					11.5
12			60				2.5	SL Odor	940				0				0	12
12.5			88				2.5		1200									12.5
13			90				1		342	SL Odor								13
13.5			61				0.5		194									13.5
14			45				0.7		389									14
14.5			55				0.6		380									14.5
15									187									15
15.5									208									15.5
									Impacted Soil Volume (cubic yards)									
	0		0		0		0		156		52		21		0		0	

Notes:
NR = No Recovery
SL = Slight
MOD = Moderate
STR = Strong

Impacted soil

Potentially impacted soil



ıbic yards)

Figure 9

Areal Distribution of Impacted Soil

Bristol-Myers Squibb Manufacturing Company
Humacao, Puerto Rico

PREPARED BY: ANDERSON - MULHOLLAND & ASSOC, INC.


P-6
P-7
P-4
P-5
I-19
I-18
I-17
I-16
TRANSECT D
(156)
(52)
P-3
I-15
I-14
I-13
I-12
TRANSECT C
(94)
I-11
I-10
I-9
I-8
TRANSECT B
P-2
(83)
P-1
I-6
I-5
I-4
(75)
I-3
(56)
TRANSECT A
EXISTING BUILDING 5
LEGEND
PLANNED BUILDING 5 EXPANSION
I-1
FOOTPRINT SOIL BORING
P-1
PERIMETER SOIL BORING
D-26
PRE-DESIGN SOIL BORING (2007)
MONITORING WELL
AREA D removal AREA
ORIGINAL SCHEDULED AREA D REMO
CELL CONTAINING IMPACTED SOIL
(156)
ESTIMATED VOLUME OF IMPACTED SC



Figure 10

Soil Vapor Sampling Results

Bristol-Myers Squibb Manufacturing Company
Humacao, Puerto Rico

PREPARED BY: ANDERSON - MULHOLLAND & ASSOC, INC.

Appendix A

Building 5 Area Supplemental Soil Investigation Boring Logs

Project: BMS- Building 5 Area | Well: I-1 | Pg. 1 of 1

Location: Humacao, PR

Drilling Co: GeoEnviroTech | Date Completed: 12/06/11

Drilling Method: Direct Push | Date Started: 12/06/11

Meas Pt/ Elev (ft amsl): N/A | Sampler / Drop: 4' by 2" Macrocore | Logged by: T. Taylor/N. Rivera

Ground Elev (ft amsl): N/A | Borehole Dia: 3.25" | Reviewed by: T. Taylor

DEPTH (ft)	PID (ppm)	SAMPLES	RECOVERY (in)	USCS Symbol	GRAPHIC LOG	SOIL DESCRIPTION
0	20 31 195 4000		0-4 24/48"	CL		(0'-2') CLAY, with some sand, and trace silt, gray, greenish, gray, and brown, moist, stiff MODERATE ODOR.
						(2'-4') NO RECOVERY.
-4	1700 1200 9999 9999 9999 3500 2800		4-7'8 40/44"	SW		(4'-7'4") SAND, coarse to fine, poorly graded, angular, with some gravel, gray to light green, moist, STRONG ODOR.
						(7'4"-7'8") NO RECOVERY.
-8						Refusal at 7'8".
-12						
-16						

ANDERSON MULHOLLAND & ASSOCIATES, INC.
Environmental Consultants
110 Corporate Park Drive
White Plains, NY 10604
914-251-0400

Notes:
40 ppm in corehole prior to sampling

Water Level ATD: N/A ft bgl | Water Level: N/A ft btc

Project: BMS- Building 5 Area | Well: I-2 | Pg. 1 of 1

Location: Humacao, PR

Drilling Co: GeoEnviroTech | Date Completed: 12/06/11

Drilling Method: Direct Push | Date Started: 12/06/11

Meas Pt/ Elev (ft amsl): N/A | Sampler / Drop: 4' by 2" Macrocore | Logged by: T. Taylor/N. Rivera

Ground Elev (ft amsl): N/A | Borehole Dia: 3.25" | Reviewed by: T. Taylor

DEPTH (ft)	PID (ppm)	SAMPLES	RECOVERY (in)	USCS Symbol	GRAPHIC LOG	SOIL DESCRIPTION
0			0-4 0/48"			(0'-4') NO RECOVERY.
-4	9999 9999 9999 9999 4790 9999 1000 903		4-8 48/48"	GP		(4'-4'3") GRAVEL, coarse, poorly graded, with some sand, light brown, moist. (4'3"-8') GRAVEL, gray and brown, wet, STRONG ODOR.
-8	1000 550 250 9999 900 132		8-12 33/48"	SM		(8'-10'11") SAND with some silt, fine, poorly graded, gray, brown, black, and red, wet, STRONG ODOR. SAMPLE I-2 (10-10.5') collected. (10'11"-12') NO RECOVERY.
-12	9999 9999 9999 1300 200 20 40		12-16 48/48"	SW		(12'-16') SAND, medium to coarse, well graded, gray, red, and black, STRONG ODOR. (Hyrdrocarbon film observed from 13'-13'5").
-16	40					End of boring at 16' ft.

ANDERSON MULHOLLAND & ASSOCIATES, INC.
Environmental Consultants
110 Corporate Park Drive
White Plains, NY 10604
914-251-0400

Notes:
10 ppm in corehole prior to sampling

Water Level ATD: N/A ft bgl | Water Level: N/A ft btc

Project: BMS- Building 5 Area | Well: I-3 | Pg. 1 of 1

Location: Humacao, PR

Drilling Co: GeoEnviroTech | Date Completed: 12/06/11

Drilling Method: Direct Push | Date Started: 12/06/11

Meas Pt/ Elev (ft amsl): N/A | Sampler / Drop: 4' by 2" Macrocore | Logged by: T. Taylor/N. Rivera

Ground Elev (ft amsl): N/A | Borehole Dia: 3.25" | Reviewed by: T. Taylor



DEPTH (ft)	PID (ppm)	SAMPLES	RECOVERY (in)	USCS Symbol	GRAPHIC LOG	SOIL DESCRIPTION
0	0 66 94		0-4 19/48"	CH		(0-1'7") CLAY, with some sand, and trace silt , light green and brown, wet. (wood fragments observed at base of sample).
						(1'7"-4) NO RECOVERY.
-4	80 155		4-8 44/48"	CH		(4'-5') CLAY, with some sand, few silt, and trace gravel, wet.
	1700 4500			GP		(5'-5'4") CLAY, with some gravel, few sand, and trace silt, wet. SAMPLE I-3 (5-6') collected. (5'4"-6'1") GRAVEL, with some sand, gray and brown, HIGH ODOR.
	700 105 671			CL		(6'1"-7'10") CLAY, with some sand, and few silt, with trace gravel at bottom 2", brownish gray, moist, HIGH ODOR.
-8						(7'10"-8') NO RECOVERY.
			8-12 0/48"			(8'-12')NO RECOVERY.
-12						(12'-12'5") NO RECOVERY.
			12-12.5 0/6"			End of Boring 12.5 ft.
-16						

ANDERSON MULHOLLAND & ASSOCIATES, INC.
Environmental Consultants
110 Corporate Park Drive
White Plains, NY 10604
914-251-0400

Notes:
0 ppm in corehole prior to sampling

Water Level ATD: N/A ft bgl | Water Level: N/A ft btc

Project: BMS- Building 5 Area | Well: I-4 | Pg. 1 of 1

Location: Humacao, PR

Drilling Co: GeoEnviroTech | Date Completed: 12/06/11

Drilling Method: Direct Push | Date Started: 12/06/11

Meas Pt/ Elev (ft amsl): N/A | Sampler / Drop: 4' by 2" Macrocore | Logged by: T. Taylor/N. Rivera

Ground Elev (ft amsl): N/A | Borehole Dia: 3.25" | Reviewed by: T. Taylor

DEPTH (ft)	PID (ppm)	SAMPLES	RECOVERY (in)	USCS Symbol	GRAPHIC LOG	SOIL DESCRIPTION
0	7000		0-4 28/48"	GM		(4"-11") GRAVEL, coarse, poorly graded, with some sand, few silt, and trace clay, dark gray to dark green.
	9999					
	9999			CL		(11"-1'6") CLAY, with some sand, few silt, and trace gravel gray to green.
	9999					(1'6"-2'6") CLAY, with some sand and trace silt, gray to reddish brown, moist, soft, STRONG ODOR.
	9999			GP		(2'6"-2'8") GRAVEL, angular.
						(2'8"-4') NO RECOVERY.
-4	3000		4-8 35/48"	GP		(4'-5'4") GRAVEL, with some sand, gray to light brown, dry. SAMPLE I-4 (5-6') collected and I-4 (5-6') dup collected.
	4000					
	9999			CL		(5'4"-6'4") CLAY, with some sand and trace silt, brown, gray, and red, moist, MODERATE ODOR.
	9999					
	1500			ML		(6'4"-6'10") SILT, with some gravel and trace sand, brown to gray.
	200					(6'10"-8') NO RECOVERY.
-8	340		8-12 31/48"	CL		(8'-9'11") CLAY, with some sand, and trace silt, gray with red veins to brown, hard, moist, MODERATE ODOR.
	860					
	670					
	536			SW		(9'11"-10'4") SAND, medium to coarse, well graded, NO ODOR.
	75					(10'4"-12') NO RECOVERY.
-12						End of Boring 12 ft.
-16						

ANDERSON MULHOLLAND & ASSOCIATES, INC.
Environmental Consultants
110 Corporate Park Drive
White Plains, NY 10604
914-251-0400

Notes:
193 ppm in corehole prior to sampling

Water Level ATD: N/A ft bgl | Water Level: N/A ft btc

Project: BMS- Building 5 Area | Well: I-5 | Pg. 1 of 1

Location: Humacao, PR

Drilling Co: GeoEnviroTech | Date Completed: 12/06/11

Drilling Method: Direct Push | Date Started: 12/06/11

Meas Pt/ Elev (ft amsl): N/A | Sampler / Drop: 4' by 2" Macrocore | Logged by: T. Taylor/N. Rivera

Ground Elev (ft amsl): N/A | Borehole Dia: 3.25" | Reviewed by: T. Taylor



ANDERSON MULHOLLAND & ASSOCIATES, INC.
Environmental Consultants
110 Corporate Park Drive
White Plains, NY 10604
914-251-0400

Notes:
600 ppm in corehole prior to sampling

Water Level ATD: N/A ft bgl | Water Level: N/A ft btc

Project: BMS- Building 5 Area | Well: I-6 | Pg. 1 of 1

Location: Humacao, PR

Drilling Co: GeoEnviroTech | Date Completed: 12/06/11

Drilling Method: Direct Push | Date Started: 12/06/11

Meas Pt/ Elev (ft amsl): N/A | Sampler / Drop: 4' by 2" Macrocore | Logged by: T. Taylor/N. Rivera

Ground Elev (ft amsl): N/A | Borehole Dia: 3.25" | Reviewed by: T. Taylor

DEPTH (ft)	PID (ppm)	SAMPLES	RECOVERY (in)	USCS Symbol	GRAPHIC LOG	SOIL DESCRIPTION
0	200		0-4 26/48"	SP		(0"-11") SAND, medium, poorly graded, with some gravel, rust brown, dry, NO ODOR.
	438					
	127			SM		(11"-2'2") SAND, fine, poorly graded, with some silt, and trace gravel, green, moist, NO ODOR.
	360					
						(2'2"-4') NO RECOVERY.
-4	129		4-8 37/48"	SM		(4'-5'1") SAND, fine, poorly graded, with some silt, and trace gravel, green, moist, NO ODOR. (May be slough from above).
	240					
	450					(5'1"-7'1") SAND, fine, poorly graded, with some silt, and trace clay, brown to gray, NO ODOR.
	428					
	160					
	300					
						(7'1"-8') NO RECOVERY.
-8	1380		8-12 31/48"	SM		(8'-8'6") SAND, fine, poorly graded, with some silt, and trace clay, brown to gray, SLIGHT ODOR.
	911					(8'6"-10'3") SAND, fine to medium, well graded, with some silt, green, brown, and trace pink, SLIGHT ODOR. SAMPLE I-6 (8.5-9.5') collected.
	995					
	420					
	18					(10'3"-10'7") SAND, fine, poorly graded, with some silt, gray, moist, NO ODOR.
						(10'7"-12') NO RECOVERY.
-12				SM		(12'-12'2") SAND, fine, poorly graded, with some silt, gray, moist, NO ODOR.
	590			SW		(12'2"-12'10") SAND, fine to medium, well graded, gray to green, wet, MODERATE ODOR.
	40		12-16 27/48"	ML		(12'10"-13'6") SILT, with some clay, dark brown, medium, SLIGHT ODOR.
	310			SM		(13'6"-13'10) SAND, fine, poorly graded, with some silt, gray, moist, NO ODOR.
	0			ML		(13'10"-14'3") SILT, with some clay, gray, soft, NO ODOR.
						(14'3"-16') NO RECOVERY.
-16						End of Boring at 16 ft.

ANDERSON MULHOLLAND & ASSOCIATES, INC.
Environmental Consultants
110 Corporate Park Drive
White Plains, NY 10604
914-251-0400

Notes:
1 ppm in corehole prior to sampling

Water Level ATD: N/A ft bgl | Water Level: N/A ft btc

Project: BMS- Building 5 Area | Well: I-7 | Pg. 1 of 1

Location: Humacao, PR

Drilling Co: GeoEnviroTech | Date Completed: 12/06/11

Drilling Method: Direct Push | Date Started: 12/06/11

Meas Pt/ Elev (ft amsl): N/A | Sampler / Drop: 4' by 2" Macrocore | Logged by: T. Taylor/N. Rivera

Ground Elev (ft amsl): N/A | Borehole Dia: 3.25" | Reviewed by: T. Taylor



DEPTH (ft)	PID (ppm)	SAMPLES	RECOVERY (in)	USCS Symbol	SOIL DESCRIPTION
0	9		0-4 38/48"		(0'-1'6") Backfill, soil mixed with rock fragments, gravel fragments of concrete.
	4				
	15			ML	(1'6"-2') SILT, with some sand, and trace gravel, brown to green.
	11				
	18			CH	(2'-3'2") CLAY, with some sand, and trace silt, brown, gray, and dark gray, wet, soft, NO ODOR.
	36				
					(3'2"-4') NO RECOVERY.
-4	50			SP	(4'-4'11") SAND, with some gravel, and trace clay, brown to gray, moist.
	21		4-8 36/48"		
	38			GP	(4'11"-5'7") GRAVEL, angular, with some sand, brown, dry, NO ODOR.
	66			SP	(5'7"-5'10") SAND, coarse, poorly graded, green, moist.
	20			SM	(5'10"-7') SAND, with some silt, brown to black, MODERATE ODOR.
	70				
					(7'-8') NO RECOVERY.
-8	41			CL	(8'-9'10") CLAY, with some sand, few silt, and trace gravel brown, yellowish brown, dark gray, and gray.
	244				
	1030		8-12 40/48"		
	995				
	9999			SW	(9'10"-11'4") SAND, medium to coarse, well graded, gray, red, brown, dark gray, wet, STRONG ODOR. SAMPLE I-7 (10-11') collected.
	9999				
	2300				
					(11'4"-12') NO RECOVERY.
-12	9999			SW	(12'-12'6") SAND, medium to coarse, well graded, gray, wet, STRONG ODOR.
					End of Boring 12.5 ft.
-16					

ANDERSON MULHOLLAND & ASSOCIATES, INC.
Environmental Consultants
110 Corporate Park Drive
White Plains, NY 10604
914-251-0400

Notes:
4 ppm in corehole prior to sampling

Water Level ATD: N/A ft bgl | Water Level: N/A ft btc

Project: BMS- Building 5 Area | Well: I-8 | Pg. 1 of 1

Location: Humacao, PR

Drilling Co: GeoEnviroTech | Date Completed: 12/07/11

Drilling Method: Direct Push | Date Started: 12/07/11

Meas Pt/ Elev (ft amsl): N/A | Sampler / Drop: 4' by 2" Macrocore | Logged by: T. Taylor/N. Rivera

Ground Elev (ft amsl): N/A | Borehole Dia: 3.25" | Reviewed by: T. Taylor

DEPTH (ft)	PID (ppm)	SAMPLES	RECOVERY (in)	USCS Symbol	GRAPHIC LOG	SOIL DESCRIPTION
0	91		0-4 21/48"	GM		(0"-1') GRAVEL, with some silt, and trace sand.
	354			CL		(1'-1'5")CLAY, with some sand, few gravel, and trace silt, brown to greenish gray, moist, stiff, NO ODOR.
	484			SM		(1'5"-1'9") SAND, with some silt, and trace clay, brown, moist, NO ODOR.
						(1'9"-4') NO RECOVERY.
-4	140			SM		(4'-4'6") SAND, with some silt, and trace clay, brown, moist, NO ODOR.
	140		4-8 32/48"	ML		(4'6"-6'8") SILT, with some clay, and trace sand, black, brown, and gray, very stiff, NO ODOR.
	578					
	240					
	528					
						(6'8"-8') NO RECOVERY.
-8	824					
	636		8-12 32/48"	CL		(8'-9'9") CLAY, with some sand, and trace silt, gray to brown, moist, very stiff, SLIGHT ODOR.
	738					
	770			SW		(9'9"-10'8") SAND, medium to coarse, well graded, gray and violet, wet, MODERATE ODOR.
	1247					
						(10'8"-12') NO RECOVERY.
-12	9999		12-16 45/48"	SW		(12'-13'7") SAND, medium to coarse, well graded, gray, wet, MODERATE ODOR.
	9999					
	9999					
	2000					(13'7"-14'1") Wood fragments.
	9999			SW		(14'1"-15'1") SAND, medium to coarse, well graded, gray and red, wet, MODERATE ODOR. SAMPLE I-8 (14-15') collected.
	9999					
	1340			CL		(15'1"-15'8") CLAY, with some silt, and trace sand, gray to brown, very stiff, SLIGHT ODOR.
-16						(15'8"-16') NO RECOVERY.
						End of Boring at 16 ft.

ANDERSON MULHOLLAND & ASSOCIATES, INC.
Environmental Consultants
110 Corporate Park Drive
White Plains, NY 10604
914-251-0400

Notes:
10 ppm in corehole prior to sampling

Water Level ATD: N/A ft bgl | Water Level: N/A ft btc

Project: BMS- Building 5 Area | Well: I-9 | Pg. 1 of 1

Location: Humacao, PR

Drilling Co: GeoEnviroTech | Date Completed: 12/07/11

Drilling Method: Direct Push | Date Started: 12/07/11

Meas Pt/ Elev (ft amsl): N/A | Sampler / Drop: 4' by 2" Macrocore | Logged by: T. Taylor/N. Rivera

Ground Elev (ft amsl): N/A | Borehole Dia: 3.25" | Reviewed by: T. Taylor



DEPTH (ft)	PID (ppm)	SAMPLES	RECOVERY (in)	USCS Symbol	GRAPHIC LOG	SOIL DESCRIPTION
0	3		0-4 24/48"	GP		(0"-3") GRAVEL, with some sand, brown, wet, NO ODOR. (Backfill).
	46			SP		(3"-1'6") SAND, coarse, poorly graded, with some gravel, gray to black, NO ODOR.
	85					(1'6"- 2') CLAY, with some sand, few silt, and trace gravel, brown to gray, moist, stiff, STRONG ODOR.
	288					(2'-4') NO RECOVERY.
-4	16		4-8 31/48"	CL		(4'-4'8") CLAY, with some sand, few silt, and trace gravel, light brown, medium.
	190					(4'8"-6'7") CLAY, with some silt, and trace sand, very dark brown, gray, and brown with black veins, moist, hard, SLIGHT ODOR.
	312					
	64					
	30					(6'7"-8') NO RECOVERY.
-8	94		8-12 35/48"	SC		(8'-9'11") SAND, fine to medium, well graded, with some clay, and trace silt, gray to brown, MODERATE ODOR. SAMPLE I-9 (8.5-9.5') collected.
	330					
	81					
	90			SW		(9'11"-10'11") SAND, fine to medium, well graded, gray and red, MODERATE ODOR.
						(10'11"-12') NO RECOVERY.
-12						End of Boring at 12 ft.
-16						

ANDERSON MULHOLLAND & ASSOCIATES, INC.
Environmental Consultants
110 Corporate Park Drive
White Plains, NY 10604
914-251-0400

Notes:
17 ppm in corehole prior to sampling

Water Level ATD: N/A ft bgl | Water Level: N/A ft btc

Project: BMS- Building 5 Area | Well: I-10 | Pg. 1 of 1

Location: Humacao, PR

Drilling Co: GeoEnviroTech | Date Completed: 12/08/11

Drilling Method: Direct Push | Date Started: 12/08/11

Meas Pt/ Elev (ft amsl): N/A | Sampler / Drop: 4' by 2" Macrocore | Logged by: T. Taylor/N. Rivera

Ground Elev (ft amsl): N/A | Borehole Dia: 3.25" | Reviewed by: T. Taylor

DEPTH (ft)	PID (ppm)	SAMPLES	RECOVERY (in)	USCS Symbol	GRAPHIC LOG	SOIL DESCRIPTION
0	890		0-4 18/48"	GP		(0"-6") GRAVEL, with some sand, wet. Backfill.
	150			CL		(6"-1'6") CLAY, with some silt, and trace gravel, brown to gray, moist, soft.
	30					(1'6"-4') NO RECOVERY
-4						Refusal at 4'
-8						
-12						
-16						

ANDERSON MULHOLLAND & ASSOCIATES, INC.
Environmental Consultants
110 Corporate Park Drive
White Plains, NY 10604
914-251-0400

Notes:
No PID in concrete prior to sampling

Water Level ATD: N/A ft bgl | Water Level: N/A ft btc

Project: BMS- Building 5 Area | Well: I-12 | Pg. 1 of 1

Location: Humacao, PR

Drilling Co: GeoEnviroTech | Date Completed: 12/07/11

Drilling Method: Direct Push | Date Started: 12/07/11

Meas Pt/ Elev (ft amsl): N/A | Sampler / Drop: 4' by 2" Macrocore | Logged by: T. Taylor/N. Rivera

Ground Elev (ft amsl): N/A | Borehole Dia: 3.25" | Reviewed by: T. Taylor

DEPTH (ft)	PID (ppm)	SAMPLES	RECOVERY (in)	USCS Symbol	GRAPHIC LOG	SOIL DESCRIPTION
0	745, 922, 81, 237		0-4 26/48"	ML		(0"-2'2") SILT, with some clay, and trace gravel, brown to gray, dry, stiff, MODERATE ODOR.
						(2'2"-4') NO RECOVERY.
-4	112			ML		(4'-4'10")SILT, with some clay, and trace gravel, brown to gray, dry, stiff, NO ODOR.
	310, 61, 161		4-8 27/48"	CL		(4'10"-6'2") CLAY, with trace gravel, brown to mottled, dry, stiff, NO ODOR.
						(6'2"-6'3") SAND, fine, poorly graded, with some silt, gray, moist, MODERATE ODOR.
	521			SM		(6'3"-8') NO RECOVERY.
-8	1103, 360			CL		(8'-9') CLAY, with some sand, gray, brown, and black, moist, medium, SLIGHT ODOR.
	4000		8-12 41/48"	SW		(9'-9'6") SAND, medium to coarse, well graded, with some gravel, gray, red, and green, wet, STRONG ODOR.
	9999, 9999					(9'6"-11'5") SAND, medium to coarse, well graded, gray, red and green, wet, STRONG ODOR. SAMPLE I-12 (9.5-10.5') collected.
	400, 404					(11'5"-12') NO RECOVERY.
-12	555, 40, 22		12-16 19/48"	SW		(12'-13'7") SAND, medium to coarse, well graded, gray and red, wet, MODERATE ODOR.
						(13'7"-14'6") NO RECOVERY.
						End of Boring at 14.5 ft.
-16						

ANDERSON MULHOLLAND & ASSOCIATES, INC.
Environmental Consultants
110 Corporate Park Drive
White Plains, NY 10604
914-251-0400

Notes:
19 ppm in corehole prior to sampling

Water Level ATD: N/A ft bgl | Water Level: N/A ft btc

Project: BMS- Building 5 Area | Well: I-13 | Pg. 1 of 1

Location: Humacao, PR

Drilling Co: GeoEnviroTech | Date Completed: 12/07/11

Drilling Method: Direct Push | Date Started: 12/07/11

Meas Pt/ Elev (ft amsl): N/A | Sampler / Drop: 4' by 2" Macrocore | Logged by: T. Taylor/N. Rivera

Ground Elev (ft amsl): N/A | Borehole Dia: 3.25" | Reviewed by: T. Taylor



DEPTH (ft)	PID (ppm)	SAMPLES	RECOVERY (in)	USCS Symbol	GRAPHIC LOG	SOIL DESCRIPTION
0	11		0-4 27/48"	ML		(0-1'7") SILT, with some gravel, and few sand, gray, moist. Backfill.
	180					
	19					
	82			CL		(1'7"-2'3") CLAY, with some sand, and trace silt, gray and black patches, moist, brown, NO ODOR.
						(2'3"-4') NO RECOVERY.
-4	9.9		4-8 36/48"	CL		(4'-4'6") CLAY, with some sand, and trace silt, gray to brown, moist, soft, SLIGHT ODOR.
	38					(4'6"-5'2") CLAY, with some gravel, few sand, and trace silt, light brown, moist, soft, SLIGHT ODOR.
	40					(5'2"-6') CLAY, with some sand, brown, gray, and black, SLIGHT ODOR.
	153					
	194					(6'-6'6") CLAY, with some sand, black, gray, and brown, moist, soft, SLIGHT ODOR.
	121					(6'6"-7'8") CLAY, with some silt, and trace sand, brown, gray, and black, moist, hard, NO ODOR.
-8	50		8-12 48/48"	SW		(7'8"-12') SAND, medium to coarse, well graded, gray to red, wet, MODERATE ODOR.
	75					
	1080					
	330					
	48					
	125					
	58					
-12	50					
	440					(12'-12'9") SAND, medium to coarse, well graded, wet. SAMPLE I-13 (12.5-13.5') collected.
	637		12-16 29/48"	CL		(12'9"-13'4") CLAY, with some sand, and trace silt, gray to red, moist, NO ODOR.
	215					(13'4"-14'9") CLAY, with some silt, and trace sand, moist, medium, SLIGHT ODOR.
	218					
	60					
						(14'9"-16') NO RECOVERY.
-16						End of Boring at 16 ft.

ANDERSON MULHOLLAND & ASSOCIATES, INC.
Environmental Consultants
110 Corporate Park Drive
White Plains, NY 10604
914-251-0400

Notes:
47 ppm in corehole prior to sampling

Water Level ATD: N/A ft bgl | Water Level: N/A ft btc

Project: BMS- Building 5 Area | Well: I-14 | Pg. 1 of 1

Location: Humacao, PR

Drilling Co: GeoEnviroTech | Date Completed: 12/07/11

Drilling Method: Direct Push | Date Started: 12/07/11

Meas Pt/ Elev (ft amsl): N/A | Sampler / Drop: 4' by 2" Macrocore | Logged by: T. Taylor/N. Rivera

Ground Elev (ft amsl): N/A | Borehole Dia: 3.25" | Reviewed by: T. Taylor

DEPTH (ft)	PID (ppm)	SAMPLES	RECOVERY (in)	USCS Symbol	GRAPHIC LOG	SOIL DESCRIPTION
0	12		0-4 27/48"	GP		(0"-1'1") GRAVEL, with some sand, and trace silt, gray, wet, NO ODOR.
	234					
	39			CL		(1'1"-2'3") CLAY, with some sand, and trace silt, brown, light brown, and gray, moist, NO ODOR.
	25					
						(2'3"-4') NO RECOVERY.
-4	150		4-8 34/48"	CL		(4'-4'7") CLAY, with some sand, and trace silt, dark brown to gray, moist, stiff.
	190					(4'7"-6'10") CLAY, with some sand, and trace silt, brown, gray, dark brown, and violet, moist, hard, SLIGHT ODOR.
	168					
	382					
						(6'10"-8') NO RECOVERY.
-8	437		8-12 48/48"	CL		(8-10'7") CLAY, with some gravel, and trace silt, brown, dark brown, and gray, moist, stiff, NO ODOR. SAMPLE I-14 (8.5-9.5') collected.
	570					
	630					
	205					
	131			SW		(10'7"-12') SAND, medium to coarse, well graded, brown, gray, and red, wet, NO ODOR.
	120					
	108					
-12	201		12-16 39/48"			(12'-14'2") SAND, medium to coarse, well graded, gray to brown, wet, MODERATE ODOR.
	55					
	61					
	75					
	105					
	77			CL		(14'2"-15'3") CLAY, with some sand, and trace silt, gray, dark brown, and brown, NO ODOR.
	86					
						(15'3"-16') NO RECOVERY.
-16						End of Boring at 16 ft.

ANDERSON MULHOLLAND & ASSOCIATES, INC.
Environmental Consultants
110 Corporate Park Drive
White Plains, NY 10604
914-251-0400

Notes:
375 ppm in corehole prior to sampling

Water Level ATD: N/A ft bgl | Water Level: N/A ft btc

Project: BMS- Building 5 Area | Well: I-15 | Pg. 1 of 1

Location: Humacao, PR

Drilling Co: GeoEnviroTech | Date Completed: 12/07/11

Drilling Method: Direct Push | Date Started: 12/07/11

Meas Pt/ Elev (ft amsl): N/A | Sampler / Drop: 4' by 2" Macrocore | Logged by: T. Taylor/N. Rivera

Ground Elev (ft amsl): N/A | Borehole Dia: 3.25" | Reviewed by: T. Taylor

DEPTH (ft)	PID (ppm)	SAMPLES	RECOVERY (in)	USCS Symbol	GRAPHIC LOG	SOIL DESCRIPTION
0	12 350		0-4 14/48"	CL		(0"-1'2") CLAY, with some gravel, few sand, and trace silt, brown, light brown, gray, and light green, moist, stiff,NO ODOR.
						(1'2"-4') NO RECOVERY.
-4	924 946 480 1900 270 548		4-8 36/48"	CL		(4'-7') CLAY, with some silt, and trace sand, gray to brown, moist, hard, MODERATE ODOR. SAMPLE I-15 (5-6') collected.
						(7'-8') NO RECOVERY.
-8	402 365		8-12 40/48"	CH		(8'-9'1") CLAY, with some sand, and trace silt, gray, brown, and reddish brown, wet, medium, MODERATE ODOR.
	270 295 142 313			SW		(9'1"-11'4") SAND, medium to coarse, well graded, gray, brown, and red, wet, SLIGHT ODOR. Bottom 3" has roots.
	30					(11'4"-12') NO RECOVERY.
-12						End of Boring 12 ft.
-16						

ANDERSON MULHOLLAND & ASSOCIATES, INC.
Environmental Consultants
110 Corporate Park Drive
White Plains, NY 10604
914-251-0400

Notes:
327 ppm in corehole prior to sampling

Water Level ATD: N/A ft bgl | Water Level: N/A ft btc

Project: BMS- Building 5 Area | Well: I-16 | Pg. 1 of 1

Location: Humacao, PR

Drilling Co: GeoEnviroTech | Date Completed: 12/07/11

Drilling Method: Direct Push | Date Started: 12/07/11

Meas Pt/ Elev (ft amsl): N/A | Sampler / Drop: 4' by 2" Macrocore | Logged by: T. Taylor/N. Rivera

Ground Elev (ft amsl): N/A | Borehole Dia: 3.25" | Reviewed by: T. Taylor

DEPTH (ft)	PID (ppm)	SAMPLES	RECOVERY (in)	USCS Symbol	GRAPHIC LOG	SOIL DESCRIPTION
0	73		0-4 28/48"	GM		(0"-11") GRAVEL, with some silt, and trace sand, gray, NO ODOR.
	194					
	96			CL		(11"-2'6") CLAY, with some sand, and trace silt, brown to gray, moist, stiff, NO ODOR.
	111					
	296					(2'6"-4') NO RECOVERY.
-4	602		4-8 35/48"	CL		(4'-5'6") CLAY, with some sand, and trace silt, green, gray, and brown, moist, soft, NO ODOR.
	423					
	308					
	988					(5'6"-6'11") CLAY, with some silt, and trace sand, brown, gray, and dark brown, moist, NO ODOR. SAMPLE I-16 (6-7') collected.
	1267					
	913					(6'11"-8') NO RECOVERY.
-8	445		8-12 40/48"	CL		(8'-9'4") CLAY, with some sand, and trace silt, light brown, brown, gray, moist, stiff, NO ODOR.
	199					
	643			SC		(9'4"-10'7")SAND, medium to coarse, well graded, with some clay gray, green, and brown, moist, MODERATE ODOR.
	200					
	95			SW		(10'7"-11'3") SAND, medium to coarse, well graded, gray, red, and brown, wet, MODERATE ODOR.
	164					
	120					(11'3"-12') NO RECOVERY.
-12						End of Boring 12 ft.
-16						

ANDERSON MULHOLLAND & ASSOCIATES, INC.
Environmental Consultants
110 Corporate Park Drive
White Plains, NY 10604
914-251-0400

Notes:
247 ppm in corehole prior to sampling

Water Level ATD: N/A ft bgl | Water Level: N/A ft btc

Project: BMS- Building 5 Area | Well: I-17 | Pg. 1 of 1

Location: Humacao, PR

Drilling Co: GeoEnviroTech | Date Completed: 12/08/11

Drilling Method: Direct Push | Date Started: 12/08/11

Meas Pt/ Elev (ft amsl): N/A | Sampler / Drop: 4' by 2" Macrocore | Logged by: T. Taylor/N. Rivera

Ground Elev (ft amsl): N/A | Borehole Dia: 3.25" | Reviewed by: T. Taylor

DEPTH (ft)	PID (ppm)	SAMPLES	RECOVERY (in)	USCS Symbol	GRAPHIC LOG	SOIL DESCRIPTION
0	240		0-4 25/48"	CH		(0"-1') CLAY, with some gravel, few sand, and trace silt, brown, wet, soft, NO ODOR.
	360					
	488			CL		(1'-2'1") CLAY, with some sand, and trace silt gray, brown, and violet, moist, soft, NO ODOR.
	507					
						(2'1"-4') NO RECOVERY.
-4						(4'-4'6") CLAY, with some sand, few silt, and trace gravel, gray, brown, and reddish brown, wet, soft, NO ODOR.
	1057		4-8 33/48"	CL		(4'6"-6'9") CLAY, with some sand, and trace silt, gray, brown, dark brown, and light green, moist, very stiff, STRONG ODOR.
	3359					
	828					
	1429					
						(6'9"-8') NO RECOVERY.
-8	844			SC		(8'-9'2") SAND, medium to coarse, well graded, with some clay, gray, brown, and black, wet, STRONG ODOR.
	9999		8-12 48/48"			
	9999			SW		(9'2"-11'10") SAND, medium to coarse, well graded, wet, STRONG ODOR. (Hydrocarbon film observed). SAMPLE I-17 (10-11') collected.
	9999					
	9999					
	450					
-12	177					(12'-14') SAND, medium to coarse, well graded, gray to brown, wet, SLIGHT ODOR.
	940					
	1200		12-16 48/48"			
	342					
	194					
	389			CL		(14-16') CLAY, with some sand, and trace silt, dark brown, gray, and brown, wet, soft, SLIGHT ODOR.
	380					
	187					
-16	208					End of Boring 16 ft.

ANDERSON MULHOLLAND & ASSOCIATES, INC.
Environmental Consultants
110 Corporate Park Drive
White Plains, NY 10604
914-251-0400

Notes:
0 ppm in corehole prior to sampling

Water Level ATD: N/A ft bgl | Water Level: N/A ft btc

Project: BMS- Building 5 Area | Well: I-18 | Pg. 1 of 1

Location: Humacao, PR

Drilling Co: GeoEnviroTech | Date Completed: 12/08/11

Drilling Method: Direct Push | Date Started: 12/08/11

Meas Pt/ Elev (ft amsl): N/A | Sampler / Drop: 4' by 2" Macrocore | Logged by: T. Taylor/N. Rivera

Ground Elev (ft amsl): N/A | Borehole Dia: 3.25" | Reviewed by: T. Taylor

DEPTH (ft)	PID (ppm)	SAMPLES	RECOVERY (in)	USCS Symbol	GRAPHIC LOG	SOIL DESCRIPTION
0	3400		0-4 27/48"	GP		(0"-5") GRAVEL, light gray, wet.
	9999			CL		(5"-1'2") CLAY, with some gravel, few sand, and trace silt, gray, brown, and light green, moist, NO ODOR.
	9999					(1'2"-2'4") CLAY, with some sand, and trace silt, brown, gray, and reddish brown, moist, stiff, NO ODOR.
	4895					
	9999					(2'4"-4') NO RECOVERY.
-4	2170		4-8 45/48"	CL		(4'5"-5'4.5") CLAY, with some sand, few silt, and trace gravel, brown, gray, and violet, moist, medium, NO ODOR.
	2100					
	819					(5'4.5"-7'9")CLAY, with some sand, few silt, and trace gravel, brown, light brown, gray, moist, medium, NO ODOR. SAMPLE I-18 (7-8') collected.
	495					
	989					
	1286					
	9999					(7'9"-8') NO RECOVERY.
-8	9999					
	1			CL		(8'-8'6") CLAY, with some sand, and trace silt, brown, gray, and black, wet, soft, SLIGHT ODOR.
	2.1		8-12 25/48"	CH		(8'6"-9'2") CLAY, with some sand, and trace silt, brown, gray, and black, moist, soft, SLIGHT ODOR.
	2.2			SW		(9'2"-10'2") SAND, medium to coarse, well graded, gray to reddish brown, moist SLIGHT ODOR.
	3.8					
						(10'2"-12') NO RECOVERY.
-12	7.5		12-16 48/48"	SW		(12'-15'10") SAND, medium to coarse, well graded, gray to reddish brown, wet, SLIGHT ODOR.
	2.5					
	2.5					
	2.5					
	1					
	0.5					
	0.7					End of Boring at 16 ft.
-16	0.6					

ANDERSON MULHOLLAND & ASSOCIATES, INC.
Environmental Consultants
110 Corporate Park Drive
White Plains, NY 10604
914-251-0400

Notes:
93 ppm in corehole prior to sampling

Water Level ATD: N/A ft bgl | Water Level: N/A ft btc

Project: BMS- Building 5 Area | Well: I-19 | Pg. 1 of 1

Location: Humacao, PR

Drilling Co: GeoEnviroTech | Date Completed: 12/08/11

Drilling Method: Direct Push | Date Started: 12/08/11

Meas Pt/ Elev (ft amsl): N/A | Sampler / Drop: 4' by 2" Macrocore | Logged by: T. Taylor/N. Rivera

Ground Elev (ft amsl): N/A | Borehole Dia: 3.25" | Reviewed by: T. Taylor

DEPTH (ft)	PID (ppm)	SAMPLES	RECOVERY (in)	USCS Symbol	GRAPHIC LOG	SOIL DESCRIPTION
0	0		0-4 35/48"	GP		(0"-1") GRAVEL, gray, NO ODOR.
	0.1					
	0.5			CL		(1'-2'11") CLAY, with some sand, few silt and trace gravel, brown to gray, moist, stiff, NO ODOR.
	1.9					
	1.4					
	0.8					(2'11"-4') NO RECOVERY.
-4	0.3		4-8 48/48"	ML		(4'-5'2") SILT, with some sand, and trace gravel, light brown to gray, moist, stiff, NO ODOR.
	0.9					
	2.6			CL		(5'2"- 6'10) CLAY, with some silt, and trace sand, brown to gray, moist, stiff, SLIGHT ODOR.
	3.5					
	3.7					
	4.4					(6'10"-7'9") CLAY, with some silt, and trace sand, brown to black, moist, stiff, SLIGHT ODOR.
	2					
-8	2.3			SW		(8'-8'3") SAND, medium to coarse, well graded, dark brown, moist. SAMPLE I-19 (8-9') collected.
	205			CL		(8'3"-9') CLAY, with some sand and trace silt, brown to gray, moist, SLIGHT ODOR.
	102		8-12 48/48"			
	83			SW		(9'-12') SAND, medium to coarse, well graded, gray to red, wet, SLIGHT ODOR.
	25					
	27					
	29					
	20					
-12	33					(12'-14'6")SAND, medium to coarse, well graded, wet, gray to red, SLIGHT ODOR.
	60					
	88					
	90		12-16 36/48"			
	61					
	45					
	55			CL		(14'6"-15') CLAY, with some silt, gray to brown, moist, stiff, SLIGHT ODOR.
						(15'-16') NO RECOVERY.
-16						End of Boring at 16 ft.

ANDERSON MULHOLLAND & ASSOCIATES, INC.
Environmental Consultants
110 Corporate Park Drive
White Plains, NY 10604
914-251-0400

Notes:
0.8 ppm in corehole prior to sampling

Water Level ATD: N/A ft bgl | Water Level: N/A ft btc

Project: BMS- Building 5 Area | Well: P-1 | Pg. 1 of 1

Location: Humacao, PR

Drilling Co: GeoEnviroTech | Date Completed: 12/05/11

Drilling Method: Direct Push | Date Started: 12/05/11

Meas Pt/ Elev (ft amsl): N/A | Sampler / Drop: 4' by 2" Macrocore | Logged by: T. Taylor/N. Rivera

Ground Elev (ft amsl): N/A | Borehole Dia: 3.25" | Reviewed by: T. Taylor

DEPTH (ft)	PID (ppm)	SAMPLES	RECOVERY (in)	USCS Symbol	GRAPHIC LOG	SOIL DESCRIPTION
0	275		0-4 22/48"	SP		(0"-6") SAND, coarse, poorly graded, gray to dark gray, moist, SLIGHT ODOR.
	583			SW		
				SP		(6"-10") SAND, fine to coarse, well graded, dark gray to black, wet, SLIGHT ODOR. SAMPLE P-1 (0.5-1.5') collected.
						(10"-1'3") SAND, fine, poorly graded, bluish green, wet, SLIGHT ODOR.
						(1'3"-1'10") SAND, fine, poorly graded, with some silt, dry, NO ODOR.
						(1'10"-4') NO RECOVERY.
-4	100		4-8 25/48"	SM		(4'-6'1") SAND, fine, poorly graded, with some silt, brown to green, dry, SLIGHT ODOR.
	235					
						(6'1"-8') NO RECOVERY.
-8						End of Boring at 8 ft.
-12						
-16						

ANDERSON MULHOLLAND & ASSOCIATES, INC.
Environmental Consultants
110 Corporate Park Drive
White Plains, NY 10604
914-251-0400

Notes:

Water Level ATD: N/A ft bgl | Water Level: N/A ft btc

Project: BMS- Building 5 Area | Well: P-2 | Pg. 1 of 1

Location: Humacao, PR

Meas Pt/ Elev (ft amsl): N/A

Ground Elev (ft amsl): N/A

Drilling Co: GeoEnviroTech

Drilling Method: Direct Push

Sampler / Drop: 4' by 2" Macrocore

Borehole Dia: 3.25"

Date Completed: 12/05/11

Date Started: 12/05/11

Logged by: T. Taylor/N. Rivera

Reviewed by: T. Taylor

DEPTH (ft)	PID (ppm)	SAMPLES	RECOVERY (in)	USCS Symbol	GRAPHIC LOG	SOIL DESCRIPTION
0	15		0-4 25/48"	SP		(0"-1') SAND, coarse, poorly graded, NO ODOR. (Broken concrete fragments).
	87					
	71			SW		(1'-2'1") SAND, fine to coarse, well graded, with few gravel, greenish gray to gray, moist, NO ODOR. SAMPLE P-2 (1.5-2') collected.
	247					
						(2'1"-4') NO RECOVERY.
-4	20		4-8 33/48"	SW		(4'-5'4") SAND, fine to coarse, well graded, with few gravel, greenish gray to gray, moist, NO ODOR.
	70					
	69			SM		(5'4"-6'9") SAND, with some silt, brown to green, wet, NO ODOR.
	30					
	40					
						(6'9"-8') NO RECOVERY.
-8						End of Boring at 8 ft.
-12						
-16						

ANDERSON MULHOLLAND & ASSOCIATES, INC.
Environmental Consultants
110 Corporate Park Drive
White Plains, NY 10604
914-251-0400

Notes:
0 ppm in corehole prior to sampling

Water Level ATD: N/A ft bgl

Water Level: N/A ft btc

Project: BMS- Building 5 Area | Well: P-3 | Pg. 1 of 1

Location: Humacao, PR

Drilling Co: GeoEnviroTech | Date Completed: 12/05/11

Drilling Method: Direct Push | Date Started: 12/05/11

Meas Pt/ Elev (ft amsl): N/A | Sampler / Drop: 4' by 2" Macrocore | Logged by: T. Taylor/N. Rivera

Ground Elev (ft amsl): N/A | Borehole Dia: 3.25" | Reviewed by: T. Taylor



ANDERSON MULHOLLAND & ASSOCIATES, INC.
Environmental Consultants
110 Corporate Park Drive
White Plains, NY 10604
914-251-0400

Notes:
0 ppm in corehole prior to sampling

Water Level ATD: N/A ft bgl | Water Level: N/A ft btc

Project: BMS- Building 5 Area | Well: P-4 | Pg. 1 of 1

Location: Humacao, PR

Drilling Co: GeoEnviroTech | Date Completed: 12/05/11

Drilling Method: Direct Push | Date Started: 12/05/11

Meas Pt/ Elev (ft amsl): N/A | Sampler / Drop: 4' by 2" Macrocore | Logged by: T. Taylor/N. Rivera

Ground Elev (ft amsl): N/A | Borehole Dia: 3.25" | Reviewed by: T. Taylor



ANDERSON MULHOLLAND & ASSOCIATES, INC.
Environmental Consultants
110 Corporate Park Drive
White Plains, NY 10604
914-251-0400

Notes:
750 ppm in corehole prior to sampling

Water Level ATD: N/A ft bgl | Water Level: N/A ft btc

Project: BMS- Building 5 Area | Well: P-5 | Pg. 1 of 1

Location: Humacao, PR

Drilling Co: GeoEnviroTech | Date Completed: 12/08/11

Drilling Method: Direct Push | Date Started: 12/08/11

Meas Pt/ Elev (ft amsl): N/A | Sampler / Drop: 4' by 2" Macrocore | Logged by: T. Taylor/N. Rivera

Ground Elev (ft amsl): N/A | Borehole Dia: 3.25" | Reviewed by: T. Taylor



ANDERSON MULHOLLAND & ASSOCIATES, INC.
Environmental Consultants
110 Corporate Park Drive
White Plains, NY 10604
914-251-0400

Notes:
650 ppm in corehole prior to sampling

Water Level ATD: N/A ft bgl | Water Level: N/A ft btc

Project: BMS- Building 5 Area | Well: P-6 | Pg. 1 of 1

Location: Humacao, PR

Drilling Co: GeoEnviroTech | Date Completed: 12/05/11

Drilling Method: Direct Push | Date Started: 12/05/11

Meas Pt/ Elev (ft amsl): 3.25" | Sampler / Drop: 4' by 2" Macrocore | Logged by: T. Taylor/N. Rivera

Ground Elev (ft amsl): N/A | Borehole Dia: N/A | Reviewed by: T. Taylor

DEPTH (ft)	PID (ppm)	SAMPLES	RECOVERY (in)	USCS Symbol	GRAPHIC LOG	SOIL DESCRIPTION
0	8300 4300		0-4 30/48"	SP		(0"-1'7") SAND, fine, poorly graded, with trace gravel, dark brown to gray, dry, SLIGHT ODOR. SAMPLE P-6 (0-1') collected.
	980 950					(1'7"-2'6") SAND, fine, poorly graded, with trace gravel, reddish brown, dry, NO ODOR.
						(2'6"-4') NO RECOVERY.
-4	400			SP		(4'-4'9") SAND, fine, poorly graded, with trace gravel, reddish brown, dry, NO ODOR.
	1500 1200 1800		4-8 30/48"	SM		(4'9"-6'6") SAND, fine, poorly graded, with some silt and trace clay, dark gray to brown, dry, NO ODOR.
						(6'6"-8') NO RECOVERY.
-8						End of Boring at 8 ft.
-12						
-16						

ANDERSON MULHOLLAND & ASSOCIATES, INC.
Environmental Consultants
110 Corporate Park Drive
White Plains, NY 10604
914-251-0400

Notes:
1300 ppm in corehole prior to sampling

Water Level ATD: N/A ft bgl | Water Level: N/A ft btc

Project: BMS- Building 5 Area | Well: P-7 | Pg. 1 of 1

Location: Humacao, PR

Meas Pt/ Elev (ft amsl): N/A

Ground Elev (ft amsl): N/A

Drilling Co: GeoEnviroTech

Drilling Method: Direct Push

Sampler / Drop: 4' by 2" Macrocore

Borehole Dia: 3.25"

Date Completed: 12/05/11

Date Started: 12/05/11

Logged by: T. Taylor/N. Rivera

Reviewed by: T. Taylor

DEPTH (ft)	PID (ppm)	SAMPLES	RECOVERY (in)	USCS Symbol	GRAPHIC LOG	SOIL DESCRIPTION
0	2706 3700		0-4 28/48"	SP		(0'-1') SAND, medium, poorly graded, light to dark gray, wet, SLIGHT ODOR. SAMPLE P-7 (0-1') collected.
	130 210			SM		(1'-2'4") SAND, fine, poorly graded, with some silt and trace gravel, brown to reddish brown, dry, NO ODOR.
						(2'4"-4') NO RECOVERY.
-4	125			SP		(4'-4'6") SAND, fine, poorly graded, with trace gravel reddish brown, dry, NO ODOR.
	183		4-8 14/48"	SM		(4'6"-5'2") SAND, fine, poorly graded, with some silt, brown to gray, moist.
						(5'2"-8') NO RECOVERY.
-8						End of Boring at 8 ft.
-12						
-16						

ANDERSON MULHOLLAND & ASSOCIATES, INC.
Environmental Consultants
110 Corporate Park Drive
White Plains, NY 10604
914-251-0400

Notes:
70 ppm in corehole prior to sampling

Water Level ATD: N/A ft bgl

Water Level: N/A ft btc

Project: BMS- Building 5 Area | Well: P-8 | Pg. 1 of 1

Location: Humacao, PR

Drilling Co: GeoEnviroTech | Date Completed: 12/08/11

Drilling Method: Direct Push | Date Started: 12/08/11

Meas Pt/ Elev (ft amsl): N/A | Sampler / Drop: 4' by 2" Macrocore | Logged by: T. Taylor/N. Rivera

Ground Elev (ft amsl): N/A | Borehole Dia: 3.25" | Reviewed by: T. Taylor



ANDERSON MULHOLLAND & ASSOCIATES, INC.
Environmental Consultants
110 Corporate Park Drive
White Plains, NY 10604
914-251-0400

Notes:
180 ppm in corehole prior to sampling

Water Level ATD: N/A ft bgl | Water Level: N/A ft btc

Project: BMS- Building 5 Area | Well: P-9 | Pg. 1 of 1

Location: Humacao, PR

Meas Pt/ Elev (ft amsl): N/A

Ground Elev (ft amsl): N/A

Drilling Co: GeoEnviroTech | Date Completed: 12/08/11

Drilling Method: Direct Push | Date Started: 12/08/11

Sampler / Drop: 4' by 2" Macrocore | Logged by: T. Taylor/N. Rivera

Borehole Dia: 3.25" | Reviewed by: T. Taylor



ANDERSON MULHOLLAND & ASSOCIATES, INC.
Environmental Consultants
110 Corporate Park Drive
White Plains, NY 10604
914-251-0400

Notes:
9999 ppm in corehole prior to sampling

Water Level ATD: N/A ft bgl | Water Level: N/A ft btc

Project: BMS Humacao | Well: I-7A | Pg. of

Location: Humacao, PR

Meas Pt/ Elev (ft amsl): N/A/

Ground Elev (ft amsl): N/A

Drilling Co: Geoenvirotech | Date Completed: 2/2/2012

Drilling Method: Direct Push | Date Started: 2/2/2012

Sampler / Drop: N/A | Logged by: N. Rivera

Borehole Dia: 4' by 2" Macrocore | Reviewed by: T. Taylor



ANDERSON MULHOLLAND & ASSOCIATES, INC.
Environmental Consultants
110 Corporate Park Drive
White Plains, NY 10604
914-251-0400

Notes:
Collected TO-3/TO-15 at 4 ft bgs

Water Level ATD: N/A ft bgl | Water Level: N/A ft btc

Project: BMS Humacao | Well: A-1R3A | Pg. of

Location: Humacao, PR

Meas Pt/ Elev (ft amsl): N/A

Ground Elev (ft amsl): N/A

Drilling Co: Geoenvirotech | Date Completed: 2/2/2012

Drilling Method: Direct Push | Date Started: 2/2/2012

Sampler / Drop: N/A | Logged by: N. Rivera

Borehole Dia: 4' by 2" Macrocore | Reviewed by: T. Taylor



ANDERSON MULHOLLAND & ASSOCIATES, INC.
Environmental Consultants
110 Corporate Park Drive
White Plains, NY 10604
914-251-0400

Notes:
Collected TO-3/TO-15 at 3.5 ft bgs above the water in the borehole

Water Level ATD: 4 ft bgl | Water Level: N/A ft btc

Appendix B

Laboratory Analytical Data and Data Validation Reports (On CD)

Appendix C

2007 Area C and D Pre-Design Investigation (on CD)

Appendix D

Monitoring Well A-1R4 Well Construction Log

Project: BMS-Building 5/6 Expansion
Location: BMS
Humacao, PR
Meas Pt/ Elev (ft amsl): 19.383
Ground Elev (ft amsl): 19.626

Drilling Co: GeoEnviroTech
Drilling Method: Hollow Stem Auger
Sampler / Drop: 4 ft Macrocore
Borehole Dia: 7.25"

Well: **A-1R4** Pg. 1 of 1
Date Completed: 4/25/13
Date Started: 4/25/13
Logged by: Richard O'Reilly
Reviewed by: Terry Taylor

DEPTH (ft)	PID (ppm)	SAMPLES	RECOVERY (in)	USCS Symbol	GRAPHIC LOG	SOIL DESCRIPTION
0						(0-0.7') Concrete coring.
	0		40/40" (0.7-4')	SW		(0.7-4') SAND, some gravel, medium to coarse, well graded, light gray and brown, dry, no staining, no odor.
	0					
-4	0					
	68.8			SC		(4-5.5') SAND, some gravel, few clay, medium to coarse, well graded, light gray and brown, dry, no staining, slight odor.
	62.9		30/48" (4-8')	CL		5.5-6.5') CLAY, some sand, little gravel, dark green, moist, medium plasticity, no staining, slight odor.
	142.2					(6.5-8') No Recovery.
-8				SC		(8-9') SAND, some clay, medium, poorly graded, greenish-brown, wet, no staining, slight odor.
	81.5			CL		(9-10') CLAY, some sand, trace gravel, greenish-brown, wet, medium plasticity, no staining, slight odor.
	121.2		24/48" (8-12')			(10-12') No Recovery.
-12				CL		(12-13') CLAY, some sand, trace gravel, greenish-brown, wet, medium plasticity, no staining, slight odor.
	216		29/29" (12-14.4')	SP		(13-14.4') SAND, coarse, poorly graded, dark gray and white, wet, no staining, no odor. Three-inch piece of PVC well screen from previous version of A-1 found in sample.
	34.8					

WELL



ANDERSON MULHOLLAND & ASSOCIATES, INC.
Environmental Consultants
110 Corporate Park Drive
White Plains, NY 10604
914-251-0400

Notes:
Replacement well for A-1R3.

Water Level ATD: NA ft bgl
Water Level: 4.80 ft btc

Appendix E

Pre-Excavation Construction Debris Waste Disposal Log and Manifests (on CD)

Appendix F

Graphical Illustration of Clean and Impacted Soil within Each Cell

Depth and Volume of Clean and Impacted Soil in Each Cell
Bristol-Myers Squibb Manufacturing Company
Humacao, Puerto Rico

Cell Number	Depth of Clean Soil (ft bgs)	Volume of Clean Soil (cu yds)	Depth of Impacted Soil (ft bgs)	Volume of Impacted Soil (cu yds)
E-1S	3.0	12	10.0	26
E-1N	3.0	12	15.0	45
E-2	4.0	30	12.0	60
E-3	5.0	38	11.5	49
E-4	0.0	0	10.0	75
E-7S	8.0	83	13.0	52
E-7N	7.0	73	13.0	63
E-8S	8.0	83	12.0	42
E-8N	6.0	63	12.0	63
E-12S	2.0	21	12.5	109
E-12N	4.0	42	13.0	94
E-16S	0.0	0	13.5	140
E-16N	5.0	52	11.5	68
E-17S	9.5	99	12.0	26
E-17N	5.0	52	11.5	68
D-26W	10.0	104	13.0	32
D-26E	7.0	73	13.0	63
D-29	4.0	83	13.0	187
D-31S	8.0	83	11.0	32
D-31N	2.0	21	10.0	83
D-32S	8.0	83	13.0	52
D-32N	4.0	42	14.0	104
D-34	3.5	73	13.0	198
D-36W	10.0	104	13.0	32
D-36E	7.0	73	11.5	47
Total Cubic Yards		***1399***		***1810***


Depth
Cell E-4
Cell E-3
Cell E-2
Cell E-1
Depth
Ground Surface
0
0.5
1
1.5
2
2.5
3
3.5
4
4.5
5
5.5
6
6.5
7
7.5
8
8.5
9
9.5
10
10.5
11
11.5
12
12.5
13
13.5
14
14.5
15
15.5
Clean Depth
Clean Depth
Clean Depth
Clean Depth
396
264
E-1S
E-1N
Impacted soil interval moved to treatment cell.


Depth
Cell E-8
Cell E-7
Cell D-26
Cell D-29
Depth
Ground Surface
0
0.5
1
1.5
2
2.5
3
3.5
4
4.5
5
5.5
6
6.5
7
7.5
8
8.5
9
9.5
10
10.5
11
11.5
12
12.5
13
13.5
14
14.5
15
15.5
Clean Depth
Clean Depth
Clean Depth
Clean Depth
Clean Depth
Clean Depth
Clean Depth
E-8N
E-8S
E-7N
E-7S
D-26W
D-26E
Impacted soil interval moved to treatment cell.


Depth
Cell E-12
Cell D-31
Cell D-32
Cell D-34
Depth
Ground Surface
0
0.5
1
1.5
2
2.5
3
3.5
4
4.5
5
5.5
6
6.5
7
7.5
8
8.5
9
9.5
10
10.5
11
11.5
12
12.5
13
13.5
14
14.5
15
15.5
Clean Depth
Clean Depth
Clean Depth
Clean Depth
Clean Depth
Clean Depth
Clean Depth
E-12N
E-12S
D-31N
D-31S
D-32N
D-32S
Impacted soil interval moved to treatment cell.


Depth
Cell E-17
Cell E-16
Cell D-36
Depth
Ground Surface
0
0.5
1
1.5
2
2.5
3
3.5
4
4.5
5
5.5
6
6.5
7
7.5
8
8.5
9
9.5
10
10.5
11
11.5
12
12.5
13
13.5
14
14.5
15
15.5
Clean Depth
Clean Depth
Clean Depth
Clean Depth
Clean Depth
Clean Depth
E-17N
E-17S
E-16N
E-16S
D-36W
D-36E
Impacted soil interval moved to treatment cell.

Appendix G

Analytical Laboratory and Data Validation Reports (on CD)

Appendix H

Perimeter Air Monitoring Results (on CD)